

Please be sure to read before use.

#### About Restrictions for NPI Integration Driver Ver.1.0

[NPI Integration Driver r Ver.1.0 Restrictions] are mentioned below,

There are following restrictions in addition to restrictions described in user's manual. When in use, please understand following content well.

Thank you very much for your understanding.

#### — Restrictions —

##### 【contents of restrictions】

- Please apply to Service Pack 2 or after when in use of Microsoft Windows XP.  
Also when using before Service Pack 2, please use it with adequate patch.
- Necessary to apply after [.net FramWork2.0]
- When use NiiPrinerLib.dll in[.net FramWork1.1], there may be need for error  
Suppression by the application.
- At the serial connection, there may be a case to print “??”at the time when activate  
OS, restart from hibernation or sleep.
- It is unwarrantable at the multi user usage on Windows XP.
- It is impossible to get the accurate status at the usage of plural printer drivers into the single port.
- Driver set up should be done by administrator.
- It does not correspond to replace users at the usage of shared printer.
- About the log file that be generated, there will be no data in case of opening the file  
during output to log file.
- At the serial connection, temporarily ,there is a case to interpret as Off-Line,  
when repeating turn on and off of (including software-reset) the printer.
- There is a logging function about Port IN/OUT, but, In/Output is unwarrantable.
- There are cases about the items that do not support by printer, even, this driver dose.
- To install the driver again, please reboot the computer at first.
- Please note that you can not use plural printers with Bluetooth connection,  
and the combination of Bluetooth and COM connection.
- Please note that there are case of taking time approximate 5~60 seconds, (rarely more than 60 seconds)  
at the transition of [ONLINE to OFFLINE] or [OFFLINE to ONLINE]  
(Please check the transition of ONLINE/OFFLINE by the status indication.)

Regards,

NIPPON PRIMEX INC.